



JWI LOUVRES – CLIENT ADVICE

Date: 18/5/2017

Job Number: 13038

Project: ASPIRE APARTMENTS

Mark,

There has been a lot of damage done to the louvres from over tightening of the louvre system.

To **OPEN** the louvres you turn the gearbox in an **ANTI-CLOCKWISE** direction.

To **CLOSE** the louvres you turn the gearbox in an **CLOCKWISE** direction.

The louvres are **not a full blackout system and cannot be forced closed**. When the blades shut they are not to be cranked any further closed. Even if there are light gaps between some of the blades they are not to be cranked so much that they bend the aluminium components. Please see attached photos of damaged components.

Damaged caused by incorrect operation is not covered by JWI Louvres warranty.



Regards,

Andrew Gore
JWI Louvres
0421 712 111

JWI Louvres (NSW) Pty. Ltd.
4 Hallstrom Place, Wetherill Park NSW 2164 Australia Telephone (02) 9757 7600 Facsimile (02) 9725 2817