




ASPIRE APARTMENTS CAR PARKING FACILITY KPI'S (Ver5)

- During the week of **27/7/2026** (7 days), there were **138** movements (a movement is calling your car or parking your car and the system completing a full cycle).
- There were **5** calls to OptiPark Service for issues that required attention from a technician during this period. These calls are broken down as follows:

User caused issues	Software related issue	Hardware related issue	Major outage (on-site visit)	TOTAL
1	4	0	0	5

- Taking the above data, **3.62%** represents the magic number for that week. This percentage means that out of all the times the facility is used, only this percentage of the time required intervention (either being a user fault and/or system issues). Klaus MultiParking Service intervention was required. System uptime was **96.38%** for the week.

Historical Data – 1 JAN 2024 to 27 JUL 2026



ALL TIME AVERAGE TO DATE (Jan 2017 - PRESENT): 1.4%
SYSTEM UPTIME: 98.6%

Notes: The rules around the use of this car parking facility are there for YOUR benefit – please follow them! **Disable any motion sensor alarm in your vehicle prior to parking.**